



Repair Methods - *Note Engineers Parts Costings Used		
Blend:	Tailgate	
New:	Door Mld O/S/F, Door Shell O/S/F, Wing/Quarter Panel O/S	
<u>Repair Cost Breakdown</u>		<u>Savings</u>
Labour Cost	<b>£784.00</b>	No Savings Associated with this claim
Parts Cost	486.75	
Paint etc	<b>£223.87</b>	
Specialist	<b>£0.00</b>	
<b>Total Ex VAT</b>	<b>£1494.62</b>	
VAT @ 15	£224.19	<u>Glass's Guide Information</u>
<b>Total Inc VAT</b>	<b>£1718.81</b>	<i>Glass's Type</i> Glass`s Older Car
		<i>Glass's Edition</i> jan 2009
		<i>Glass's Code</i> VQJM
		<i>Glass's Guide Mileage</i> 110000
		<i>Dealer Retail (Overall)</i> £725
		<i>Private Sale (Overall)</i> £490
		<i>Disposal (Overall)</i> £160

Conclusions
We anticipate further damage would be revealed on dismantling.

We trust the above is of assistance to you and enclose a note of our fee for your attention.

Yours Faithfully,  
Chris Jones  
AAE, MIMI. Eng Tech, MIRTE. MSOE. MIBE. LCGI. MSAE.  
Member of the Society of Expert Witnesses  
Affiliate Member of the Trading Standards Institute

On behalf of C Jones Consulting Motor Engineers

66 New Street, Porthmadog, Gwynedd, LL49 9EE - Tel 01766 515 942 - Fax 01766 569 011. Website www.cjones.co.uk

**Statement of Truth**

'We declare that we understand our duty in providing this report to the court and we confirm that we have complied with that duty. We understand that this duty overrides any other obligation. Our report is based upon the instructions received. We confirm that insofar as the facts stated in our report are within our own knowledge we have made clear which they are and believe them to be true and that the opinions we have expressed represent our true and complete professional opinion. We believe that the facts as stated in this report are true and the opinions we have expressed are correct.'

Pictures

